






3489 Sawmill Road, P.O. Box 4290, Akron OH 44321-0290
fax 1-330-666-0844 - 1-330-668-2587 - 1-800-320-1841
www.PlasTEAK.com

Grab Ladder Assembly Diagrams



PlasTEAK®

3489 Sawmill Road, P.O. Box 4290, Akron OH 44321-0290
fax 1-330-666-0844 - 1-330-668-2587 - 1-800-320-1841
www.PlasTEAK.com



Assemble ladder as shown
Slide step onto rope, add
spaces then the next step
repeating for all parts. Knot
rope ends using Figure 8
knot shown below.
Twist steps to store.
Ladder can be hung from loop
end or knotted end depending
on available support.

Figure 8 knot for rope ends

